

# Gammauno calibration procedure: XE, XS, XF, XT, XN, XC controllers

The instrument calibration is based on a series of steps. Each step performs the calibration of a particular input or output. Calibration is normally not necessary, when calibration is necessary high accuracy reference instruments must be used. After calibration the instrument must remain powered on at the environmental conditions for minimum 1 hour.

